ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
3

Ward Name
Atturu

Street ID
W0319, W0200, W0315, W0337, W0202, W0351, W0214, W

Street Name
11th Crs Lakshmi Sagar Lyt, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, NA, S Krishnap

Significant Landmark
Escorts Eng. Layout 1st main and Cross Roads

Segment No.
3/S-W0319/S102138

Total Length (m)
475.56

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	49.78	77.567146	13.103220	77.567157	13.102770	W0212	W0216
2	35.72	77.566889	13.103397	77.567216	13.103361	W0212	W0212
3	172.10	77.566602	13.104745	77.567961	13.104748	W0299	W0200
4	217.96	77.569638	13.104432	77.569295	13.102491	W0200	W0216

Work Details

History of Road / Lane / Circles

Name of the Work
Asphalting to Roads and Improvements to Drain in Escorts Eng. Layout 1st main and Cross Roads in ward no 03 Yelahanka Satellite Town Sub division Yela

Sanctioned Estimated Amount (Rs.)
5000000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details
Asphalting to Roads and Improvements to Drain in Escorts Eng. Layout 1st main and Cross Roads in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

Job No. / Work Code
003-17-000007

Work Order No.
BBMP/EE (YNK.D) /WO/139/2017 -18

Work Order Date
31/03/2017

Period of Extention
90 DAYS

Defect Liability Period From
30/04/2017

Defect Liability Period To
29/04/2018

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0319, W0200, W0315, W0337,

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
12		CHANDRAKANTH
Date of Inspection	**Remarks**	
24/05/2017	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0319, W0200, W0315, W0337,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/05/2017	23/06/2017	COMPLETED
SE	VASU K M	24/05/2017	23/06/2017	COMPLETED
EE	VASU K M	24/05/2017	23/06/2017	COMPLETED
AEE	ASHOK	24/05/2017	23/06/2017	COMPLETED
AE	CHANDRAKANTH	24/05/2017	23/06/2017	COMPLETED
AE	CHANDRAKANTH	24/05/2017	23/06/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0319, W0200, W0315, W0337,